

To Efrat Laser/ECI Telecom@ECI Telecom, Kohava Bentov/ECI Telecom@ECI Telecom, Shalom Bukimer/ECI Telecom@ECI Telecom, Silvio Shefer/ECI Telecom@ECI

cc Doron Karpell/ECI Telecom@ECI Telecom. Dikla Klein/ECI Telecom@ECI Telecom. Chaim Rainer/ECI Telecom. Chaim Rainer/ECI Telecom. Jeffrey Telecom. Gilad Bandel/ECI Telecom. Jeffrey

bcc

Subject Voice Management V1.5

Hi,

The attached document corrects the relationships between a user port and its bearer channels, on one hand, and the CP IWF entity (represented by the associated VCC) on the other hand.

Read, enjoy and comment.

Moti Morgenstern

Senior Systems Engineer ECI Telecoms Ltd. Broadband Access Division 30 Hasivim St. Petach Tikva, Israel 49517 Tel.: +972-3-9266258

Fax: +972-3-9287342 Cell: +972-55-786258

e-mail: Moti.Morgenstern@ecitele.com

www.ecitele.com

This transmission and any files attached to it contains confidential and/or proprietary information and is intended only for the named recipient. If you are not the intended recipient, you are hereby notified that any re-transmission, dissemination, disclosure or copying of this information is strictly prohibited.

- Voice management - CP MIB v0105.doc.zip